



## NOTICE

### 2014 and Newer Harley-Davidson® Motorcycles

#### ISSUE:


Factory radios on 2014 and newer Harley-Davidson® audio systems use a “high fidelity” EQ curve. This EQ will cause excessive distortion with any amplified audio upgrade and will lead to speaker damage.

#### SOLUTION:

Authorized Rockford Fosgate Motorcycle Dealers can “flash” your factory radio to remove this EQ.

#### WHAT TO DO:

Have your nearest Authorized Rockford Fosgate Motorcycle Dealer “flash” your radio. Factory Harley-Davidson® techs can no longer perform this software update. Find a dealer at [www.rockfordfosgate.com/dealerlocator](http://www.rockfordfosgate.com/dealerlocator). For more info contact Rockford Fosgate tech support at 1-800-669-9899.



..... Factory Harley-Davidson® Boom!™ EQ Curve  
———— Flattened EQ with Flash